ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	11	Kuvempu Nagar
Street ID	**Street Name**	**Significant Landmark**
W0660	NA	Houses
Segment No.	**Total Length (m)**	
11/S-W0660/S111802	220.86	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	220.86	77.548109	13.058556	77.546097	13.058250	Gamgamma Circle Road	Cross Road

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to Roads and Drains and Providing Covering Slabs at Ramachandrapura, Devappa Layout, Kalathur Layout, Mariyamma Block and Surrounding are	3000000	2019-20
Year	**Type of Work**	**Other Work Type**
2019 - 2020	Drain Maintenance	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Raising of Drain using solid block and providing covering slab	011-20-000119
Work Order No.	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/ E-PMT/01 (41733)/WO/119/2020-21	25/09/2020	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
11/11/2020	10/11/2021	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M.S Raju		0.00
Phone No.	**E-Mail ID**	
9448853642		

Assistant Executive Engineer
Vidyaranyapura Sub Division
BBMP, Bangalore - 97

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Somnath S Jadhav
Date of Inspection	**Remarks**	
24/11/2020		

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Sri.S.P.Ranganath	24/11/2020	23/12/2020	As proposed
SE	Vijay Kumar Haridas	24/11/2020	23/12/2020	Forwarded
EE	Mohandas H T	24/11/2020	23/12/2020	Verified
AEE	Shivakumar M Goudar	24/11/2020	23/12/2020	Verified
AE	Somnath S Jadhav	24/11/2020	23/12/2020	Mobile verification Done
AE	Somnath S Jadhav	23/11/2020	23/12/2020	Forwarded

Assistant Executive Engineer
Vidyaranyapura Sub Division
BBMP, Bangalore - 97

Zone: YELAHANKA | Ward No: 11 | Ward Name: Kuvempu Nagar | Street ID: W0660

Date: 24/11/2020 | Time: 12:23:17 | RH 20201124122317

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	11	Kuvempu Nagar
Street ID	**Street Name**	**Significant Landmark**
W0650	1st Crs	Shop
Segment No.	**Total Length (m)**	
11/S-W0650/S111642	90.66	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	90.66	77.545962	13.058539	77.546788	13.058661	Gamgamma Ciricle road	Cross Road

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to Roads and Drains and Providing Covering Slabs at Ramachandrapura, Devappa Layout, Kalathur Layout, Mariyamma Block and Surrounding are	3000000	2019-20
Year	**Type of Work**	**Other Work Type**
2019 - 2020	Drain Maintenance	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Raising of Drain using solid block and providing covering slab	011-20-000119
Work Order No.	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/ E-PMT/01 (41733)/WO/119/2020-21	25/09/2020	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
11/11/2020	10/11/2021	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M.S Raju		0.00
Phone No.	**E-Mail ID**	
9448853642		

Assistant Executive Engineer
Vidyaranyapura Sub Division
BBMP, Bangalore-97

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Somnath S Jadhav p
Date of Inspection	**Remarks**	
24/11/2020		

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Sri.S.P.Ranganath	24/11/2020	23/12/2020	As proposed
SE	Vijay Kumar Haridas	24/11/2020	23/12/2020	Forwarded
EE	Mohandas H T	24/11/2020	23/12/2020	Verified
AEE	Shivakumar M Goudar	24/11/2020	23/12/2020	Verified
AE	Somnath S Jadhav	24/11/2020	23/12/2020	Mobile Verification Done
AE	Somnath S Jadhav	23/11/2020	23/12/2020	Forwarded

Assistant Executive Engineer
Vidyaranyapura Sub Division
BBMP, Bangalore - 97

ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	11	Kuvempu Nagar
Street ID	**Street Name**	**Significant Landmark**
W0636	7th Crs	Shop
Segment No.	**Total Length (m)**	
11/S-W0636/S111206	97.85	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	97.85	77.545845	13.058819	77.546735	13.058968	Gangamma Circle Road	Cross Road

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to Roads and Drains and Providing Covering Slabs at Ramachandrapura, Devappa Layout, Kalathur Layout, Mariyamma Block and Surrounding are	3000000	2019-20
Year	**Type of Work**	**Other Work Type**
2019 - 2020	Drain Maintenance	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Raising of Drain using solid block and providing covering slab	011-20-000119
Work Order No.	**Work Order Date**	**Period of Extention**
EE/BTP/BBMP/ E-PMT/01 (41733)/WO/119/2020-21	25/09/2020	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/,Work Code #**
11/11/2020	10/11/2021	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
M.S Raju		0.00
Phone No.	**E-Mail ID**	
9448853642		

Assistant Executive Engineer
Vidyaranyapura Sub Division
BBMP, Bangalore-97

Field Inspection Details

Number of Trees	Any Other Information	Name
0		Somnath S Jadhav
Date of Inspection	**Remarks**	
24/11/2020		

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	Sri.S.P.Ranganath	24/11/2020	23/12/2020	As proposed
SE	Vijay Kumar Haridas	24/11/2020	23/12/2020	Forwarded
EE	Mohandas H T	24/11/2020	23/12/2020	Verified
AEE	Shivakumar M Goudar	24/11/2020	23/12/2020	Verified
AE	Somnath S Jadhav	24/11/2020	23/12/2020	Mobile Verification Done
AE	Somnath S Jadhav	23/11/2020	23/12/2020	Forwarded

Assistant Executive Engineer
Vidyaranyapura Sub Division
BBMP, Bangalore - 97

Zone: YELAHANKA Ward No: 11 Ward Name: Kuvempu Nagar. Street ID: W0636

Date: 24/11/2020 Time: 12:19:28 RH 20201124121928